



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director
JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
May 2, 2008

Supervisor Th

Mine Name: Freedom From War	Permit Number: S/039/0024
Operator Name: Wall & Rock, Inc.	Inspection Date: May 1, 2008
Inspector(s): Lynn Kunzler	Time: 11:00 am
Other Participants: Adam Brotherson	Mine Status: active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Routine inspection while in the area.

Inspection Summary:

This site was active during this inspection. Adam Brotherson, a recent hire, was digging stone along the northern boundary. This site was originally found mining without a permit or surety. A cessation order at that time required the operator to obtain a permit and post surety. Acceptance of the Notice for a small mining operation and approval of the surety was done on January 30, 2008. Most of the Disturbance observed last fall had been reclaimed. About 2-3 acres of current disturbance remains. (active portion of the site). There were no non-compliance issues observed at the site.

Photos were taken to document site conditions.

Conclusions and Recommendations:

This site is apparently in compliance. Continue to monitor this site when in the area.

Inspector's Signature 3-95

LK:pb

cc: Todd Wilhite, Operator.

O:\M039-Sanpete\S0390024-FreedomFromWar\inspections\Insp-05012008.doc